

**The Compatibility Test of RITEK BD-R&RE Media  
2011.5.16**

No	Drive Maker	Model Name	Write Speed	BD-R DL 4X
				RITEK DR2
1	HLDS	GBW-H10N Official Firmware GL06 (2007.10.12)	BD-R SL 4X BD-RE SL 4X	Not Supported
2	HLDS	GGW-H10N Official Firmware 1.04 (2008.4.11)	BD-R SL 4X DL 2X BD-RE SL 2 DL 2X	2X
3	HLDS	GGW-H20N Official Firmware XJ04	BD-R SL 6X DL 4X BD-R LTH 2X BD-RE SL 2X DL 2X	Not Supported
4	HLDS	GGW-H20L Official Firmware YL05	BD-R SL 6X DL 4X 2X BD-R LTH BD-RE SL 2 DL 2X	Not Supported
5	HLDS	BH08NS20 Official Firmware EL02	BD-R SL 8X DL 8X 2X BD-R LTH BD-RE SL 2 DL 2X	Not Supported
6	HLDS	BH08LS20 Official Firmware 2.00	BD-R SL 8X DL 8X 2X BD-R LTH BD-RE SL 2 DL 2X	Not Supported
7	HLDS	BH10NS30 Official Firmware EL00-09	BD-R SL 10X DL 8X 6X BD-R LTH BD-RE SL 2 DL 2X	4X
8	HLDS	BH12NS30 Official Firmware EL00	BD-R SL 12X DL 12X 6X BD-R LTH BD-RE SL 2 DL 2X	4X
9	HLDS	BH12LS30 Official Firmware 1.00	BD-R SL 12X DL 12X 6X BD-R LTH BD-RE SL 2 DL 2X	4X
10	Panasonic	SW-5582 Official Firmware BZB9	BD-R SL 2X DL 2X BD-RE SL 2 DL 2X	2X
11	Panasonic	LF-PB271 Official Firmware 1.02	BD-R SL 4X DL 4X BD-RE SL 2 DL 2X	4X
12	Panasonic	SW-5584 Official Firmware 1.00	BD-R SL 8X DL 8X BD-RE SL 2 DL 2X	4X
13	Panasonic	LF-PB371JD Official Firmware 1.02	BD-R SL 8X DL 8X BD-RE SL 2 DL 2X	4X
14	PLDS(LITEON)	LH-2B1S Official Firmware AL09	BD-R SL 2X DL Not Supported BD-RE SL 2 DL Not Supported	Not Supported
15	PLDS(LITEON)	DH-4B1S Official Firmware 7P5A	BD-R SL 4X DL Not Supported BD-RE SL 2 DL Not Supported	Not Supported
16	PLDS(LITEON)	iHBS 112 Official Firmware CL0J	BD-R SL 12X DL 8X BD-RE SL 2 DL 2X	4X
17	PLDS(LITEON)	iHBS 212 Official Firmware 5L08	BD-R SL 12X DL 8X BD-RE SL 2 DL 2X	4X
18	PLEXTOR	PX-B900A Official Firmware	BD-R SL 2X DL 2X	2X

No	Drive Maker	Model Name	Write Speed	BD-R DL 4X
				RITEK DR2
		1.01	BD-RE SL 2 DL 2X	
19	PLEXTOR	PX-B910SA Official Firmware 1.00	BD-R SL 4X DL 4X  BD-RE SL 2 DL 2X	4X
20	PLEXTOR	PX-B920SA Official Firmware 1.03	BD-R SL 4X DL 4X 2X BD-R LTH BD-RE SL 2 DL 2X	Not Supported
21	PLEXTOR	PX-B940SA Official Firmware 1.08	BD-R SL 12X DL 12X 6X BD-R LTH BD-RE SL 2 DL 2X	4X
22	PIONEER	BDR-101A Official Firmware 1.00	BD-R SL 2X DL 2X  BD-RE SL 2 DL 2X	Not Supported
23	PIONEER	BDR-202 Official Firmware 1.08	BD-R SL 4X DL 4X  BD-RE SL 2 DL 2X	Not Supported
24	PIONEER	BDR-203 Official Firmware 1.13	BD-R SL 8X DL 8X  BD-RE SL 2 DL 2X	4X
25	PIONEER	BDR-205 Official Firmware 1.11	BD-R SL 12X DL 12X 6X BD-R LTH BD-RE SL 2 DL 2X	8X
26	PIONEER	BDR-206 Official Firmware 1.05	BD-R SL 12X DL 12X 6X BD-R LTH BD-RE SL 2 DL 2X	8X
27	PIONEER	BDR-206MBK Official Firmware 1.03	BD-R SL 12X DL 12X 6X BD-R LTH BD-RE SL 2 DL 2X	4X
28	PIONEER	BDR-TD03 Official Firmware 8.00	BD-R SL 12X DL 12X 6X BD-R LTH BD-RE SL 2 DL 2X	4X
29	SONY	BWU-100A Official Firmware (2007.04.17)	BD-R SL 2X DL 2X  BD-RE SL 2 DL 2X	2X
30	SONY	BWU-200S Official Firmware 1.0b	BD-R SL 4X DL 4X  BD-RE SL 2 DL 2X	4X
31	SONY	BWU-300S Official Firmware 1.0b	BD-R SL 8X DL 8X  BD-RE SL 2 DL 2X	4X
32	SONY	BWU-500S Official Firmware 1.63	BD-R SL 12X DL 8X 6X BD-R LTH BD-RE SL 2 DL 2X	4X
33	SONY	BD-5730S Official Firmware 1.02	BD-R SL 6X DL 4X 6X BD-R LTH BD-RE SL 2 DL 2X	4X